



Clay Electric Cooperative, Inc.

February 1, 2018

Wesley Taylor
Capital Circle Office Center
2540 Shumard Oak Boulevard
Tallahassee, Florida 32399-0850

Re: Docket No. 20170215-EU - Review of Electric Utility Hurricane Preparedness and Restoration Actions

Dear Mr. Taylor:

Below are Clay Electric Cooperative, Inc.'s responses to the 3rd set of hurricane data request questions.

1. Please provide the following information for a specific example where storm hardened structures incurred damage and required repair or replacement due to Hurricane Irma.
 - a. A description of the damage incurred (i.e. broken pole, displaced underground vault, etc.). Not applicable. Not aware of any storm hardened structures that were damaged.
 - b. A description of the repair process, including a description of any temporary repairs that required a follow-up trip. Not applicable.
 - c. A description of the repair process if the facilities had not been hardened. Broken poles would be replaced in same location with applicable length, class, and type pole. Replaced materials are removed from the site and disposed of appropriately. Work is recorded and documented for plant accounting and potential storm reimbursement purposes. Other damaged facilities would be handled through the same process.

Should you have any questions, feel free to call me.

Sincerely,

Frank R Holmes

Frank R. Holmes, P.E.
Chief Operating Officer

FRH\kc

Enclosure