

Review of Electric Utility Hurricane Preparedness and Restoration Actions

Docket No : 20170215-EU

Name : DAVID weston

Electric Utility Provider : FPL

Zip Code : 33176

Category : Information provided by electric utility provider prior to the storm

Comments : In general and over the last FIVE years we have had service problems at 10411 SW 123 ST Miami FL 33176. We lost power early Saturday morning and it was restored 10 days later. However one house east of us had power. The South side of 123 street had power. Three doors down to the West of us had power. One-half block north had power.

Our little section lost power BEFORE the storm. I have been working now with FPL representative Blanca Nodar for FIVE years to eliminate power outages in our little alcove. Squirrels have frequently been blamed. They must be the rare type of underground squirrels because our power comes from underground and a pad mounted transformer.

There is no excuse for 5 years of service interruption. Wouldn't you agree ?