

November 15, 2021

ELECTRONIC FILING

Mr. Adam J. Teitzman, Commission Clerk Florida Public Service Commission 2540 Shumard Oak Boulevard Tallahassee, FL 32399-0850

Re: Docket No. 20110320-GU Petition for approval of Cast Iron / Bare Steel Pipe Replacement Rider (Rider CI/BSR), by Peoples Gas System

Dear Mr. Teitzman:

Enclosed for filing on behalf of Peoples Gas System and in accordance with Order No. PSC-12-0476-TRF-GU, please find the quarterly progress report for replacement of cast iron / bare steel and plastic pipe facilities during third quarter 2021.

Sincerely,

Derrick MacDonald, CPA Manager, Regulatory Affairs

Peoples Gas System

Enclosure

cc: Robert Graves, Chief, Safety Bureau

Andrew M. Brown

Kandi Floyd

Peoples Gas System July - September 2021 Quarterly Report Cast Iron / Bare Steel Replacement Activity

Ret. Year	Ret. Month	n Work Order No	Work Order Description/Location	Asset Type	Division	Miles	Count
2021	Jul	Bare Steel Service Retirement	Bare Steel Service Retirement	Bare Steel Service	DADE-BROWARD		2
2021	Jul	D0098188	Frazar Rd Main Replacement	Plastic Aldyl A	DAYTONA	0.036259	
2021	Aug	D0065540	Central Ave BS 2018-2020	Bare Steel	ST PETE	0.008028	
2021	Aug	D0098752	Stranded short sections of CI/BS Ma	Bare Steel	ST PETE	0.038353	
2021	Aug	Bare Steel Service Retirement	Bare Steel Service Retirement	Bare Steel Service	TAMPA		2
2021	Sep	D0098752	Stranded short sections of CI/BS Ma	Bare Steel	ST PETE	0.104287	
2021	Sep	D0098752	Stranded short sections of CI/BS Ma	Other	ST PETE	0.009260	
2021	Sep	Bare Steel Service Retirement	Bare Steel Service Retirement	Bare Steel Service	TAMPA		1
					Total	0.196188	5

Summary

Mains (Miles)

iums (iimes)							
Month	Miles Replaced	Bare Steel	Cast Iron	Aldyl	Other		
Jul	0.04	0.00	0.00	0.04	0.00		
Aug	0.05	0.05	0.00	0.00	0.00		
Sep	0.11	0.10	0.00	0.00	0.01		
Total	0.20	0.15	0.00	0.04	0.01		

Services

00.11000							
Month	Miles Replaced	Bare Steel	Cast Iron	<u>Aldyl</u>	Other		
Jul	2	2					
Aug	2	2					
Sep	1	1					
Total	5	5	0	0	0		

Note: Replacement may fluctuate due to timing of project completion