


What's Wrong With This Picture?



































































































A photograph of a pipeline facility. In the foreground, a chain-link fence runs across the frame. Behind the fence, there are several large pipes. A prominent horizontal pipe is painted red, with two vertical pipes also painted red rising from it. Above these, there are more pipes, some of which are grey and show signs of rust. A white sign with a yellow header is attached to the fence. The background consists of a dense line of green trees and foliage.

Pipeline Company

For Emergencies Call:



A Wide Shot for Perspective (note the severely sloped driveway)







