

John T. Butler Senior Attorney Florida Power & Light Company 700 Universe Boulevard Juno Beach, Florida 33408 (561) 304-5639

April 28 2008

#### VIA HAND DELIVERY

Ms. Ann Cole, Commission Clerk Florida Public Service Commission 2540 Shumard Oak Boulevard Tallahassee, Florida 32399-0850

080000-07 28 PH I2:

Re: Quarterly report of customer interruptions and curtailments.

Dear Ms. Cole:

Enclosed please find Florida Power & Light Company's ("FPL") quarterly Report of Customer Interruptions and Curtailments for the quarter ending March 31, 2008 in accordance with Rule 25-6.018(3), F.A.C. As the Commission is aware, at 1:09 pm on Tuesday, February 26, 2008, an incident occurred in the FPL service area that caused some FPL customers to lose power. The peak number of FPL customers without power was approximately 596,000, with an average outage time of approximately one hour for affected customers. Although some Curtailable Service (CS) customers were affected by this event, FPL did not specifically curtail CS customers during the event.

Also enclosed with this letter are documents that were provided to the CMP \_\_\_\_\_ Commission Staff in accordance with Rule 25-6.018(2), F.A.C., concerning the February 26 incident. These documents were provided as soon as practicable and as they became COM available. FPL's investigation of this incident is ongoing. FPL will continue to provide \_\_\_\_ information to the Commission Staff on the incident as it becomes available. CTR \_\_\_\_

Please acknowledge your receipt of this filing as provided in the Commission's electronic filing procedures. Thank you for your assistance in this matter.

OPC RCA

GCL

ECR

SCR

SGA \_\_\_\_\_ Enclosures SEC

OTH \_\_\_\_\_

Respectfully. John T. Butler

DECUMENT NUMBER-DATE 03417 APR 28 3 **FPSC-COMMISSION CLERK** 

		Flo	rida Po	wer & Lig	ht Compa	ny			
Report of Customer Interruptions and Curtailments									
Rule 25-6.018 (3)									
Reporting Period: 1st Qtr 2008									
Interruptions During Quarter? Yes X No # Events 0									
Rate Class	Date of	Start Time	End Time	Duration	Load Shed (MW) @ Gen	Reason fr	or Interruption		
CS-1									
CS-2	· · · ·								
CS-3							· · · · · · · · · · · · · · · · · · ·		
CST-1									
CST-2									
CST-3	· · · · · · · · · · · · · · · · · · ·								
Total					0				
Continuity of Serv	vice Available?		Yes		No				
Continuity of	Date of	Start	End	1	MWh's @	Cost /			
Service Details	Purchase	Time	Time	Duration	Gen	Mwh	Source		

Completed By: Ernie Plasencia

Date: <u>4/3/2008</u>

DOCUMENT NUMBER-DATE

03417 APR 28 8

Page 1 of 1

-

4

FPSC-COMMISSION CLERK

U.S. Department of Energy Electricity Delivery and Energ Form OE-417 (2005)	y Reliability	ELECTRIC EMERGENCY INCIDENT AND DISTURBANCE REPORT	Form Approved OMB No. 1901-0288 Approval Expires 10/31/08				
NOTICE: This report is mandator law. For the sanctions and the provi Title 18 USC 1001 makes it a crit false, fictitious, or fraudulent state	y under Public Law sions concerning the ninal offense for a ments as to any ma	93-275. Failure to comply may result in criminal fine e confidentiality of information submitted on this form ny person knowingly and willingly to make to any atter within its jurisdiction.	es, civil penalties and other sanctions as provided by see General Information portion of the instructions Agency or Department of the United States an				
<b>RESPONSE DUE:</b> Submit a Scheet the incident. Submit updates as need	lule 1 as an Emerger ted and a final repor	t (Schedules 1 and 2) within 48 hours. Electronic subr	v. All other initial reports are due within 6 hours of nission is the preferred method of submission.				
	SCHEI	DULE 1 ALERT NOTICE (page	ge 1 of 2)				
<u>Criteria for Filing</u> (Check all that apply)	1. [         ] Actual           2. [         ] Actual	physical attack that causes major interruptions or impa cyber or communications attack that causes major inte	ets to critical infrastructure facilities or to operation. rruptions of electrical system operations				
If any box 1-8 on the right is checked, this form must be filed	3. [ ] Comple	te operational failure or shut-down of the transmission	and/or distribution electrical system				
Emergency Alert (for the Alert Status) on Line 1 below.	blacked out area	a or within the partial failure of an integrated electrical system					
If any box 9-12 on the right is checked AND none of the boxes 1-	incident						
8 are checked, this form must be filed within 6 hours of the incident; check Normal Alert (for the Alert	6. [ ] Load sr 7. [ ] System-	<ul> <li>[ ] Load shedding of 100 Megawaits of more implemented under emergency operational policy</li> <li>[ ] System-wide voltage reductions of 3 percent or more</li> <li>[ ] Public appeal to reduce the use of electricity for purposes of maintaining the continuity of the electric power stem</li> </ul>					
Status) on Line 1 below. If significant changes have	8. [ ] Public a system						
occurred after filing the initial report, refile the form with the changes and check Update (for the	9. [ ] Suspect target component	ed physical attacks that could impact electric power sy s of any security systems	stem adequacy or reliability; or vandalism which				
48 hours after an incident occurs	10. ] Suspect	ed cyber or communications attacks that could impact	electric power system adequacy or vulnerability				
refile the form with the latest information and check Final (for the Alert Status) on Line 1 below.	11. [x] Loss o	relectric service to more than 50,000 customers for 1 oply emergencies that could impact electric power syst	nour or more em adequacy or reliability				
LINE ORGANIZATION FILI	IG						
1.         Alert Status (check one)		Emergency Alert [ ] Normal Alert 1 Hour 6 Hours	Update     Final       As required     48 Hours				
2. Organization Name		Florida Power & Light					

	Organization ( and						
3.	Address of Principal Business Office	4200 West Flagler St Miami Fl					
	NAME OF OFFICIAL THAT NEEDS TO BE	CONTACTED FOR FOLLOW-UP AND ANY ADDITIONAL IN	FORMATION				
4.	Name Don McInnis						
5.	Title	Manager, Operations Engineering					
6.	Telephone Number	(305)-(442)-(5272)					
7.	FAX Number	( 305 )-( 442 )-( )	<u></u>				
8.	E-mail Address	Don_mcinnis@FPL.com					
9.	Teleconference Number	( )-( )-( ) Passcode	] Video [ ]				
	INCIDENT AND DISTURBANCE DATA		· · ·				
10.	Geographic Area(s) Affected	Primary Dade County Fl.	Unknown [ ]				
11.	Date/Time Incident Began (mm-dd-yy/hh:mm) using 24-hour clock	<u>02</u> - <u>26</u> - <u>2008</u> / <u>13</u> : <u>09</u> mo dd yy hh mm					
12.	Estimated Date/Time of Restoration (mm-dd-yy/hh:mm) using 24-hour clock	0226200819_ /00 : mo dd yy hh mm	Unknown				
13.	Date/Time Incident Ended (mm-dd-yy/ hh:mm) using 24-hour clock	mo dd yy hh mm					
14.	Did the incident/disturbance originate in your system/area? (check one)	Yes [ x ] No [ ]	Unknown [ ]				
15.	Estimate of Amount of Demand Involved (Megawatts)	3000MW	Unknown [ ]				
16.	Estimate of Number of Customers Affected	850,000 Unknown [ ]					
17.	Internal Organizational Tracking Number (if applicable)	N.A.					

SCHEDULE 1 ALERT NOTICE (page 2 of 2)								
18. Type of Emergency Check all that apply	19. Cause of Incident Check if known or suspected	20. Actions Taken Check all that apply						
Major Physical Attack [ ]	Complete Electrical System Failure [ ]	Shed Firm Load [x]						
Major Cyber Attack []	Electrical System Separation – Islanding [ ]	Reduced Voltage [ ]						
Major Transmission System Interruption [ x ]	Inadequate Electric Resources to Serve Load [ x ]	Made Public Appeals [ ]						
Major Generation Inadequacy [ ]	Actual or Suspected Malicious/Intentional Physical [] Cyber/Computer/Telecom [] Vandalism []	Implemented a Warning, Alert, or Contingency Plan []						
Major Distribution System Interruption [ ]	Transmission Equipment [x]	Shed Interruptible Load [ ]						
Other []	Loss of Part or All of a High Voltage Substation or Switchyard (230 kV + for AC 200 kV+ for DC).	Repaired/Restored [ ]						
	Weather or Natural Disaster	Other []						
	Operator Action(s)       []         Fuel Supply Deficiency (e.g., gas, oil, water)[       ]         Unknown Cause       []							
	Other							

,

The timely submission of Form OE-417 by those required to report is mandatory under Section 13(b) of the Federal Energy Administration Act of 1974 (FEAA) (Public Law 93-275), as amended. Failure to respond may result in a penalty of not more than \$2,750 per day for each civil violation, or a fine of not more than \$5,000 per day for each civil violation. The government may bring a civil action to prohibit reporting violations, which may result in a temporary restraining order or a preliminary or permanent injunction without bond. In such civil action, the court may also issue mandatory injunctions commanding any person to comply with these reporting requirements. Title 18 U.S.C. 1001 makes it a criminal offense for any person knowingly and willingly to make to any Agency or Department of the United States any false, fictitious, or fraudulent statements as to any matter within its jurisdiction.

A person is not required to respond to collection of information unless the form displays a valid OMB number. Data reported on Form OE-417 in Schedule 1, lines 4, 5, 6, 7, 8, and 9 are considered to be confidential. Schedule 2 is considered confidential. All other data are not confidential. (See form General Instructions for a full list of legal citations covering data collection authorization.)

U.S. Department of Energy Electricity Delivery and Energy Reliability Form OE-417 (2005)

ELECTRIC EMERGENCY INCIDENT AND DISTURBANCE REPORT

#### Form Approved OMB No. 1901-0288 Approval Expires 10/31/08

## SCHEDULE 2. – NARRATIVE DESCRIPTION

Provide a description of the event and actions taken to resolve it. Include as appropriate, the cause of the incident/disturbance, equipment damaged, critical infrastructures interrupted and effects on other systems. Be sure to identify: the name of any lost high voltage substations or switchyards, whether there was any electrical system separation (and if there were, what the islanding boundaries were), and the name of the generators and voltage lines that were lost (shown by capacity type and voltage size grouping). If necessary, copy and attach additional sheets. Equivalent documents, containing this information can be supplied to meet the requirement; these include the NERC Disturbance Report and the voluntary National Critical Infrastructure Protection System Form. Along with the filing of Schedule 2, a final (updated) Schedule 1 needs to be filed. Check the Final box on line 1 for Alert Status on Schedule 1 and submit this and the completed Schedule 2 no later than 48 hours after the event.

21. Narrative:

At 13:09 on 2/26/2008 FPL lost approximately 3000MW of load impacting 850,000 customers. FPL lost 35 transmission lines in Dade county. Approximately 2400MW of generation also tripped.

The loss of generation resulted in underfrequency operation within the state of Florida. The bulk of the load lost by FPL was in Dade county due to the openning of transmission lines. Underfrequency operation shed load throughout FPL's service territiry

Restoration of transmission lines and the associated customer begin within 15 minutes of the interruption. All essential customer load has been restored.

All load in FPL's Northern area has been restored. Restoration of load in Dade, Broward and Palm Beach counties is being delayed due to inadequeate generation due to the earlier loss. The ability to bring power into the effected areas is limited due to a planned maitenance outage of a 500kV line.

As generation is returned to service additional load is being restored. All load is expected to be restored by 21:00 on 2/26/08.

Additional reports to follow

ame of Generator(s) and		
Voltage Line(s) system		
eference (terminal points)		
for these losses, please group by energine type and voltage size)		
enerator type and tonage size,		

U.S. Department of Energy			EII	ELECTRIC EMERCENCY INCIDENT FO				Form Approved		
Electr	icity Delivery and Energy	y Reliability	ELI	AND DISTUDD	JENCI I ANCE DI	INCIDENT EDODT	OMB No. 1901-0288			
Form	OE-417 (2005)			AND DISTURDA	HNCE AI	CFURI	Appro	val Expires 10/	31/08	
NOTIC	<b>CE:</b> This report is mandator	y under Public Lav	93-27	5. Failure to comply	may result	in criminal fines,	civil pena	ilties and other sanc	tions as provided by	
law. Fo	or the sanctions and the provis	sions concerning th	e confic	dentiality of informati	on submitte	d on this form, s	ee General	Information portio	n of the instructions.	
false fi	of the second states of the st	ments as to any m	ny per. atter w	thin its jurisdiction	willingly to	make to any A	gency or	Department of the	e United States any	
RESPO	DNSE DUE: Submit a Sched	ule 1 as an Emerge	ncv Ale	ert report within 1 hou	r if for inci	dents 1-8 below.	All other	initial reports are du	e within 6 hours of	
the inci	dent. Submit updates as need	ed and a final repor	t (Sche	edules 1 and 2) within	48 hours.	Electronic submis	ssion is the	e preferred method	of submission.	
		SCHEI	DUL	E 1 ALER	RT NO	TICE (page	1 of 2)			
		1. [ ] Actual	physica	al attack that causes m	ajor interru	ptions or impacts	to critical	infrastructure facil	ities or to operations	
<u>Criteri</u> (Check	a for Filing all that apply)	2. [ ] Actual	cyber o	or communications att	ack that cau	ises major interru	ptions of e	electrical system op	erations	
If any b	ox 1-8 on the right is	3. [ ] Comple	te opera	ational failure or shut-	down of th	e transmission an	d/or distri	bution electrical sys	tem	
within 1	hour of the incident: check	4. [ ] Electric	al Syste	em Separation (Island	ling) where	part or parts of a	nower gri	d remain(s) operatio	onal in an otherwise	
Emergency Alert (for the Alert blacked out area or w				in the partial failure o	f an integra	ted electrical syst	lem			
Status)	on Line I below.	5. [ x ] Uncon	trolled l	loss of 300 Megawatt	s or more o	f firm system loa	ds for mor	e than 15 minutes f	rom a single	
If any b	ox 9-12 on the right is	incident							-	
8 are ch	ecked, this form must be	6. [] Load sh	nedding	ng of 100 Megawatts or more implemented under emergency operational policy						
filed wit	thin 6 hours of the incident;	7 [ ] Sustan								
Status) (	on Line 1 below.	7. [ ] System	-wide v	follage reductions of 3	percent or	more				
10-110	•	8. [ ] Public a	ppeal to	o reduce the use of ele	etricity for	purposes of mair	ntaining th	e continuity of the e	electric power	
If signif	tafter filing the initial	system								
report, r	efile the form with the	9. [ ] Suspect	ed phys	hysical attacks that could impact electric power system adequacy or reliability; or vandalism which						
changes	and check Update (for the	target component	s of any	any security systems						
Alert Sta	atus) on Line 1 below.	10 L L Suspect	ed cybe	er or communications	attacks that	could impact ele	etric now	er system adequacy	or vulnerability	
48 hours	s after an incident occurs	Tott Jourpeer	eu eybe	er of communications	utuens the			er system udequitey	or vunctuonity	
refile the	e form with the latest	11. [ x ] Loss o	felectr	tric service to more than 50,000 customers for 1 hour or more						
the Aler	tion and check Final (for	12 [ ] Epel su	anly em	mergencies that could impact electric nower system adequacy or reliability						
	t Status) on Enter Fociow.	12:[ ] 100/30]		ingenoies that could i						
LINE NO.	ORGANIZATION FILIN	G				· · · · · · · · · · · · · · · · · · ·				
1.	Alert Status (check one)			Emergency Alert [ 1 Hour	1	Normal Alert [ 6 Hours	]	Update [ ] As required	Final [ X ] 48 Hours	
2.	Organization Name			Florida Power & Lig	ht					
3. Address of Principal Business Office				4200 West Flagler St	Miami Fl					
	NAME OF OFFICIAL TH	BE CO!	ONTACTED FOR FOLLOW-UP AND ANY ADDITIONAL INFORMATION							
4.	I. Name			Don McInnis						
5.	Title			Manager, Operations Engineering						
6.	Telephone Number			(305)-(442)-	<u>·( 5272</u>	)				
7.	FAX Number			( 305 )-( 442 )-( 5022 )						
8.	E-mail Address			Don_mcinnis@F	PL.com					
9.	releconference Number		1	()-())		Passcode		Video		

. .

1.	r AA Number		
8.	E-mail Address	Don_mcinnis@FPL.com	
9.	Teleconference Number	( )-( )-( ) Passcode [	Video [
	INCIDENT AND DISTURBANCE DATA		
10.	Geographic Area(s) Affected	Primary Dade County Fl.	Unknown [ ]
11.	Date/Time Incident Began (mm-dd-yy/hh:mm) using 24-hour clock		
12.	Estimated Date/Time of Restoration (mm-dd-yy/ hh:mm) using 24-hour clock	0226200816/_30: moddyyhhmm	Unknown [ ]
13.	Date/Time Incident Ended (mm-dd-yy/ hh:mm) using 24-hour clock		
14.	Did the incident/disturbance originate in your system/area? (check one)	Yes   x   No   ]	Unknown [ ]
15.	Estimate of Amount of Demand Involved (Megawatts)	3200MW	Unknown [ ]
16.	Estimate of Number of Customers Affected	584, 384	Unknown [ ]
17.	Internal Organizational Tracking Number (if applicable)	N.A.	

SCHEDULE 1 ALERT NOTICE (page 2 of 2)								
18. Type of Emergency Check all that apply	19. Cause of Incident Check if known or suspected	20. Actions Taken Check all that apply						
Major Physical Attack [ ]	Complete Electrical System Failure [ ]	Shed Firm Load [x]						
Major Cyber Attack []	Electrical System Separation – Islanding [ ]	Reduced Voltage [ ]						
Major Transmission System Interruption [ x ]	Inadequate Electric Resources to Serve Load [ x ]	Made Public Appeals [ ]						
Major Generation Inadequacy [ ]	Actual or Suspected Malicious/Intentional         Physical       [         Cyber/Computer/Telecom       [         Vandalism       [	Implemented a Warning, Alert, or Contingency Plan []						
Major Distribution System Interruption [ ]	Transmission Equipment [ x ]	Shed Interruptible Load [ ]						
Other []	Loss of Part or All of a High Voltage Substation or Switchyard (230 kV + for AC 200 kV+ for DC).	Repaired/Restored [ ]						
	Weather or Natural Disaster [ ]	Other []						
	Operator Action(s)							
	Fuel Supply Deficiency (e.g., gas, oil, water)							
	Unknown Cause	_						
	Other							
The timely submission of Form OE-41/ by those requ	ired to report is mandatory under Section 13(b) of the may result in a penalty of not more than $22.750$ and $dc$	Federal Energy Administration Act of 1974 (FEAA)						
\$5,000 per day for each criminal violation. The gover	nment may bring a civil action to prohibit reporting vi	olations, which may result in a temporary restraining						

.

.

order or a preliminary or permanent injunction without bond. In such civil action, the court may also issue mandatory injunctions commanding any person to comply with these reporting requirements. Title 18 U.S.C. 1001 makes it a criminal offense for any person knowingly and willingly to make to any Agency or Department of the United States any false, fictitious, or fraudulent statements as to any matter within its jurisdiction.

A person is not required to respond to collection of information unless the form displays a valid OMB number. Data reported on Form OE-417 in Schedule 1, lines 4, 5, 6, 7, 8, and 9 are considered to be confidential. Schedule 2 is considered confidential. All other data are not confidential. (See form General Instructions for a full list of legal citations covering data collection authorization.)

U.S. Department of Energy Electricity Delivery and Energy Reliability Form OE-417 (2005)

ELECTRIC EMERGENCY INCIDENT AND DISTURBANCE REPORT Form Approved OMB No. 1901-0288 Approval Expires 10/31/08

## SCHEDULE 2. – NARRATIVE DESCRIPTION

Provide a description of the event and actions taken to resolve it. Include as appropriate, the cause of the incident/disturbance, equipment damaged, critical infrastructures interrupted and effects on other systems. Be sure to identify: the name of any lost high voltage substations or switchyards, whether there was any electrical system separation (and if there were, what the islanding boundaries were), and the name of the generators and voltage lines that were lost (shown by capacity type and voltage size grouping). If necessary, copy and attach additional sheets. Equivalent documents, containing this information can be supplied to meet the requirement; these include the NERC Disturbance Report and the voluntary National Critical Infrastructure Protection System Form. Along with the filing of Schedule 2, a final (updated) Schedule 1 needs to be filed. Check the Final box on line 1 for Alert Status on Schedule 1 and submit this and the completed Schedule 2 no later than 48 hours after the event.

21. Narrative:

At 13:09 an equipment failure at an FPL substation facility in Dade county created a three phase fault on the system. The fault caused the loss of generating units plus the tripping of transmission lines. Approximately 3200MW of load was lost impacting an estimated 584,384 customers.

The loss of generation resulted in underfrequency operation within the state of Florida. The bulk of the load lost by FPL was in Dade county due to the opening of transmission lines

Restoration of transmission lines and the associated customer begin within 15 minutes of the interruption. By 15:00 all transmission lines have been restored. By 16:11 all feeders were restored. Residential load management and commercial industrial load control were active in Dade, Broward and Palm Beach counties until roughly 19:00.

Initial restoration of generation that tripped started at 16:49 with the return to service of CT at Turkey Point.

, , , , , , , , , , , , , , , , , , , ,	Generators That Tripped Turkey Point #3 (715MW), Turkey Point #4(710MW), Turkey Point #5(1092MW) Martin 8ACT, Martin 8BCT, Martin 8CCT(total 700MW), Lauderdale 5ACT(220) Transmission line effected:
Name of Generator(s) and Voltage Line(s) system reference (terminal points) (For these losses, please group by generator type and voltage size)	StationStationANDYTOWNLINEFLAGAMI_230KVDADELINEFLAGAMI_138KVDORALTIEDADE_REC_230KVGALLOWAYLINESOUTH_MIAMI_138KVMIAMILINEMIAMI_BEACH_138KVRAILWAYLINEMIAMI_BEACH_138KVRAILWAYLINEMIAMI_T138KVRAILWAYLINERIVERSIDE_138KVRIVERSIDELINEFLAGAMI_#1_138KVRIVERSIDELINEFLAGAMI_#2_138KVRIVERSIDELINEFLAGAMI_#2_138KVRIVERSIDELINEFLAGAMI_#2_230KVTURKEY_POINTLINEFLAGAMI_138KVSOUTH_MIAMILINEFLAGAMI_138KVVILLAGE_GREENLINEFLAGAMI_138KVMIAMI_BEACHLINEFLAGAMI_230KVCOURTLINECUTLER_138KVDAVISLINECUTLER_138KVDAVISLINECUTLER_138KVMiamiLineGallowayMiamiLineSimpsonFlagamiLineMiami #1FlagamiLineMiami #1FlagamiLineMiami #2Coconut GroveLineRiversideCoconut GroveLineSouth MiamiCutlerLineSouth MiamiCutlerLineSouth Miami
	Single End TripsGARDENLINELITTLE_RIVER_138KVLAUDERDALELINEGRATIGNY_138KVMIAMILINERAILWAY_#2_138KVMIAMI_SHORESLINELITTLE_RIVER_138KVTURKEY_POINTLINEDAVIS_#2_230KVVENETIANLINERONEY_69KVLEVEELINETURKEY_POINT_230KV
Identify Name of Lost High Voltage Substation(s) and/or Switchyards (230 kV + for AC 200 kV + for DC)	Transmission Stations Impacted         Coconut Grove         Flagami         Riverside         Cutler         Riverside         Miami         South Miami         Galloway

Identify	None	
Electrical		
System		
Separation:		
Boundaries		
Doundurity		
(DOE needs a basic		
description/understa		
generating resources		
to load pockets.)		
	Page	of

### NERC Interconnection Reliability Operating Limit and Preliminary Disturbance Report

1.	Organization filing report.	Florida Power & Lig	ght		
2.	Name of person filing report.	Frank Prieto			
3.	Telephone number.	305-442-5920			
4.	Date and time of disturbance.				
	Date:(mm/dd/yy)	02/26/08			
	Time/Zone:	13:09 EST			
5.	Did the disturbance originate in your system?	Yes 🛛 No 🗌			
6.	Describe disturbance including: cause, equipment damage, critical services interrupted, system separation, key scheduled and actual flows prior to disturbance and in the case of a disturbance involving a special protection or remedial action scheme, what action is being taken to prevent recurrence.	Failure of switch that connected an inductor at FPL's Flagami 138KV switchyard. No equipment damage other than switch. No system separation occurred. No special protection schemes operated.			
7.	Generation tripped.				
	MW Total	3238 MW			
	List generation tripped	Turkey Point #3 and #4 (1425 MW), Turkey Point #5 (1092 MW), Martin #8 (502 MW), Lauderdale #5A CT (220 MW)			
8.	Frequency.				
	Just prior to disturbance (Hz):	60			
	Immediately after disturbance (Hz max.):	60.65			
	Immediately after disturbance (Hz min.):	59.39			
9.	List transmission lines tripped (specify voltage level of each line).	see attachment A			
10.		FIRM	INTERRUPTIBLE		
	Demand tripped (MW):	3200 MW	None		
	Number of affected Customers: Demand lost (MW-Minutes):	475,000 (estimated)	None		
		ТВD	None		
11.	Restoration time.	INITIAL	FINAL		
	Transmission:	13:09:21	14:53:41		
	Generation:	17:32	23:05		
	Demand:	13:18	16:11		

Check here if this is an Interconnection Reliability Operating Limit (IROL) violation report.

.

,

	Date	Time	<b>Reporting Station</b>	From Bus		To Bus			TIME CLOSED
1	8/2/2026	13.09.13	ANDYTOWN	ANDYTOWN	LINE	FLAGAMI_230KV	TRML	OPEN	13:26:47
2	8/2/2026	13.09.13	DADE	DADE	LINE	FLAGAMI_138KV	TRML	OPEN	13:28:21
3	8/2/2026	13.09.13	DORAL	DORAL	TIE	DADE_REC_230KV	TRML	OPEN	14:53:41
4	8/2/2026	13.09.13	GALLOWAY	GALLOWAY	LINE	SOUTH_MIAMI_138KV	TRML	OPEN	14:03:37
5	8/2/2026	13.09.13	GARDEN	GARDEN	LINE	LITTLE_RIVER_138KV	TRML	OPEN	13:09:21
6	8/2/2026	13.09.13	LAUDLE	LAUDERDALE	LINE	GRATIGNY_138KV	TRML	OPEN	13:09:21
8	8/2/2026	13.09.13	MIAMI	MIAMI	LINE	MIAMI_BEACH_138KV	TRML	OPEN	14:32:20
9	8/2/2026	13.09.13	MIAMI	MIAMI	LINE	RAILWAY_#2_138KV	TRML	OPEN	14:24:03
10	8/2/2026	13.09.13	RAILWAY	RAILWAY		MIAMI_#1_138KV	TRML	OPEN	14:24:39
11	8/2/2026	13.09.15	AIRPORT	AIRPORT	LINE	RIVERSIDE_138KV	TRML	OPEN	13:29:17
12	8/2/2026	13.09.15	MIAMI_SH	MIAMI_SHORI	LINE	LITTLE_RIVER_138KV	TRML	OPEN	13:38:37
13	8/2/2026	13.09.15	RIVRSIDE	RIVERSIDE	LINE	AIRPORT_138KV	TRML	OPEN	13:29:17
14	8/2/2026	13.09.15	RIVRSIDE	RIVERSIDE	LINE	FLAGAMI_#1_138KV	TRML	OPEN	13:31:19
15	8/2/2026	13.09.15	RIVRSIDE	RIVERSIDE	LINE	FLAGAMI_#2_138KV	TRML	OPEN	13:33:55
16	8/2/2026	13.09.15	TKY_PT	TURKEY_POI	LINE	DAVIS_#2_230KV	TRML	OPEN	13:09:21
17	8/2/2026	13.09.15	TKY_PT	TURKEY_POI	LINE	FLAGAMI_#1_230KV	TRML	OPEN	13:39:25
18	8/2/2026	13.09.15	TKY_PT	TURKEY_POI	LINE	FLAGAMI_#2_230KV	TRML	OPEN	13:43:20
19	8/2/2026	13.09.15	VLG_GREN	VILLAGE_GRE	LINE	FLAGAMI_138KV	TRML	OPEN	13:40:17
20	8/2/2026	13.09.17	S_MIĀMI	SOUTH_MIAM	LINE	FLAGAMI_138KV	TRML	OPEN	14:11:54
21	8/2/2026	13.09.17	VENETIAN	VENETIAN	LINE	RONEY_69KV	TRML	OPEN	14:36:04
22	8/2/2026	13.09.21	MIA_BCH	MIAMI_BEACH	LINE	MIAMI_69KV	TRML	OPEN	14:33:49
23	8/2/2026	13.09.25	LEVEE	LEVEE	LINE	FLAGAMI_230KV	TRML	OPEN	13:26:09
24	8/2/2026	13.09.25	LEVEE	LEVEE	LINE	TURKEY_POINT_230KV	TRML	OPEN	13:38:33
25	8/2/2026	13.12.20	COURT	COURT	LINE	CUTLER_138KV	TRML	OPEN	13:49:56
26	8/2/2026	13.12.20	COURT	COURT	LINE	DAVIS_138KV	TRML	OPEN	13:49:56
27	8/2/2026	13.12.20	DAVIS	DAVIS	LINE	CUTLER_#4_138KV	TRML	OPEN	13:52:52

.

# FRCC Preliminary Disturbance Report - Supplemental Data Request

This data will be used to complete a Regional investigation of the event.

FRCC Regional Event Date: February 26<sup>th</sup> 2008, approx. 1309 EST

. .

•

1.	Revision date:	02/27/08 @5:30 PM	
	(of this data and attached "NERC IROL and Preliminary Disturbance Report")		
2.	System Load Immediately prior to event:	15,200 MW	
3.	Actual UFLS Load Shed:	892 MW	
	Total amount (MW):		
	No. of feeders:	503 Feeders	
	Step setting for the feeders:	59.70 Hz	
	Ratio: no. of feeders tripped / no. of feeders set for each step.	116/223 (under investigation)	
4.	Any significant voltage excursions on your system (± 10%): List by Substation:	None post fault	
	Max. volts: Min. volts:		
5.	List any actual SOL or IROL conditions on your system as result of the event:	None	

6.	Please attach any relevant frequency or voltage plots that you feel will help in the investigation of the event, to this report: Note: Include sampling rate and equipment used to produce the plot.	Will be provided with later report
7.	Any Misoperations coincident with this event:	Under investigation
8.	Additional comments:	None

#### The UFLS Program Set-points are provided as a reference:

. . . .

UFLS	Frequency	Time Delay	Amount of Load (% of	Cumulative Amount
Step	- (hertz)	- (seconds)	member system)	of Load (°e)
A	59.7 <sup>2</sup>	0.28	9	ò
В	59.4	0.28		16
С	59.1	0.28	7,	23
D	58.8	0.28	6	29
E	58.5	0.28	5	34
F	58.2	0.28	7	41
L	59.4	10.0	j	46
M	59.7	12.0	5	51
N	59.1	8.0	5	56

Deviations from the FRCC UFLS schedule must be assessed by the FRCC. Local area changes 2. in the UFLS assignments must be compatible with the overall underfrequency protection for the FRCC

<sup>&</sup>lt;sup>1</sup> Time Delay = Intentional delay + relay delay + breaker delay <sup>2</sup> FPL has 2/2 of Step A set at 59.82 hertz as an aid to system stability. This high set Step A is concentrated in the Miami area.

# **FPL Interim Measures**

- Provided refresher training to P&C field engineers on the established practice of not disabling all protection for energized equipment.
- Modified procedures to require two P&C field engineers to sign off on job risk assessment at all substations when any relay protection is disabled.
- In addition, changed work practices to require that a second P&C field engineer be present when relay protection is disabled at transmission substations.
- Conducted training on new and modified procedures with all P&C field personnel.



